

**Takotna: Airport Relocation****FY2005 Request: \$5,111,000****Reference No: 39179****AP/AL:** Allocation**Project Type:** Construction**Category:** Transportation**Location:** Takotna**Contact:** Kip Knudson**House District:** Interior Villages (HD 6)**Contact Phone:** (907)269-0724**Estimated Project Dates:** 07/01/2004 - 06/30/2009**Appropriation:** Airport Improvement Program**Brief Summary and Statement of Need:**

Construct a new airport 1.3 miles east of Takotna. Construct a new runway, safety area, apron, taxiway, support area, and an equipment storage building. Install runway lighting. This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods.

<b>Funding:</b>	<b>FY2005</b>	<b>FY2006</b>	<b>FY2007</b>	<b>FY2008</b>	<b>FY2009</b>	<b>FY2010</b>	<b>Total</b>
Fed Rcpts	\$5,111,000						\$5,111,000
<b>Total:</b>	<b>\$5,111,000</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$5,111,000</b>

<input checked="" type="checkbox"/> State Match Required	<input checked="" type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
7% = Minimum State Match % Required		<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

**Operating & Maintenance Costs:**

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	0
<b>Totals:</b>	<b>0</b>	<b>0</b>

**Additional Information / Prior Funding History:**

None.

**Project Description/Justification:**

The runway, apron and taxiway do not meet state standards for a community class airport. The runway safety area is inadequate and does not meet current standards. There are obstructions in the approach zone, and the runway does not meet current dimensional standards for length, width, and grade. The aircraft parking area is simply a widened portion of the runway; it should be located in the object free area. Airport lighting will improve operations and safety during hours of limited visibility and darkness. Currently the airport lacks maintenance facilities. The Yukon Kuskokwim Area Plan recommends a runway length of 4,000' at this airport based on the lack of barge service and the need for fuel shipments.