

Ekwok: Snow Removal Equipment Building**FY2006 Request: \$820,000**
Reference No: 40554**AP/AL:** Allocation**Project Type:** Construction**Category:** Transportation**Location:** Ekwok**Contact:** Kip Knudson**House District:** Bristol Bay/Aleutians (HD 37)**Contact Phone:** (907)269-0724**Estimated Project Dates:** 07/01/2005 - 06/30/2010**Appropriation:** Airport Improvement Program**Brief Summary and Statement of Need:**

Demolish existing 2-bay Snow Removal Equipment Building (SREB) and construct new heated 2-bay SREB with a concrete floor. This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods.

| Funding: | <u>FY2006</u> | <u>FY2007</u> | <u>FY2008</u> | <u>FY2009</u> | <u>FY2010</u> | <u>FY2011</u> | <u>Total</u> |
|-----------------|---------------|---------------|---------------|---------------|---------------|---------------|--------------|
| Fed Rcpts | \$820,000 | | | | | | \$820,000 |
| Total: | \$820,000 | \$0 | \$0 | \$0 | \$0 | \$0 | \$820,000 |

| | | | | |
|--|--|---------------------------------------|---|-----------------------------------|
| <input checked="" type="checkbox"/> State Match Required | <input checked="" type="checkbox"/> One-Time Project | <input type="checkbox"/> Phased - new | <input type="checkbox"/> Phased - underway | <input type="checkbox"/> On-Going |
| 5% = Minimum State Match % Required | | <input type="checkbox"/> Amendment | <input type="checkbox"/> Mental Health Bill | |

Operating & Maintenance Costs:

| | <u>Amount</u> | <u>Staff</u> |
|----------------------|---------------|--------------|
| Project Development: | 0 | 0 |
| Ongoing Operating: | 0 | 0 |
| One-Time Startup: | 0 | 0 |
| Totals: | 0 | 0 |

Additional Information / Prior Funding History:

None.

Project Description/Justification:

The existing 2-bay snow removal equipment building was built in 1979 and is 26 years old. It is a metal building that is unheated, uninsulated, and drafty. The roll-up doors do not work properly. It has a dirt floor, wood foundation, and is subject to hazardous material spills. This building needs to be demolished and replaced. Additional equipment needed to maintain the airport requires more space to be properly maintained and stored. Currently there is a grader with attachments. Funding has been requested for a new loader with attachments.