

Emergency and Non-Routine Repairs**FY2008 Request: \$85,000****Reference No: AMD 30634****AP/AL:** Appropriation**Project Type:** Health and Safety**Category:** Transportation**Location:** Statewide**Contact:** Frank Richards**House District:** Statewide (HD 1-40)**Contact Phone:** (907)465-3900**Estimated Project Dates:** 04/13/2008 - 09/30/2009**Brief Summary and Statement of Need:**

Supplemental funding for emergency and non-routine expenditures associated with boardwalk repairs in the community of Solomon. These repairs are ineligible for federal reimbursement. This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods.

Funding:	FY2008	FY2009	FY2010	FY2011	FY2012	FY2013	Total
Gen Fund	\$85,000						\$85,000
Total:	\$85,000	\$0	\$0	\$0	\$0	\$0	\$85,000

<input type="checkbox"/> State Match Required	<input type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input checked="" type="checkbox"/> On-Going
0% = Minimum State Match % Required		<input checked="" type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

Operating & Maintenance Costs:

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	0
Totals:	0	0

Additional Information / Prior Funding History:

FY2007 - \$250,000; FY2005 Supplemental - \$573,400; FY2003 - \$700,000; FY2002 - \$600,000; FY2001 - \$600,000; FY2000 - \$600,000; FY1999 - \$500,000.

Project Description/Justification:**Solomon Boardwalk \$85,000**

In 2004 the Bering Sea storm caused extensive damage to Solomon. This community is located on the west bank of the Solomon River, 30 miles east of Nome. The Department of Homeland Security and Emergency Management and the Federal Emergency Management Administration (FEMA) inspected the project and approved repairs to the boardwalk. However, when departmental engineers inspected the project in 2006, there was approximately 152 feet of boardwalk missing from the Solomon Wayside Interpretive Center. The interpretative wayside provides visitors with information on the significant mining events that occurred in this area. There are several old steam engines that are on display - as well as interpretative signs describing the historical activity. The most likely cause of the boardwalk damage was from a storm in 2005. Unfortunately, the additional 2005 damage went undetected and is not eligible for FEMA participation. Repairs to these facilities are necessary so that FEMA eligible work can also take place.