

Yakutat - Airport Runway, Taxiway and Apron Rehabilitation

FY2015 Request: \$10,000,000
Reference No: 58648

AP/AL: Allocation

Project Type: Construction

Category: Transportation

Location: Yakutat

House District: Kodiak/Cordova (HD 35)

Impact House District: Kodiak/Cordova (HD 35)

Contact: Steven Hatter

Estimated Project Dates: 07/01/2014 - 06/30/2021

Contact Phone: (907)269-0730

Appropriation: Airport Improvement Program

Brief Summary and Statement of Need:

This project will include milling and patching the existing surface, and the construction of a new surface that is designed to mitigate the effects of the high groundwater. Additional work will include pavement improvements in adjacent taxiway and apron areas as necessary.

Funding:	<u>FY2015</u>	<u>FY2016</u>	<u>FY2017</u>	<u>FY2018</u>	<u>FY2019</u>	<u>FY2020</u>	<u>Total</u>
Fed Rcpts	\$10,000,000						\$10,000,000
Total:	\$10,000,000	\$0	\$0	\$0	\$0	\$0	\$10,000,000

<input checked="" type="checkbox"/> State Match Required	<input checked="" type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
3% = Minimum State Match % Required		<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

Operating & Maintenance Costs:

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	
Totals:	0	0

Prior Funding History / Additional Information:

No prior funding history

Project Description/Justification:

Pavement on Yakutat’s primary runway has a low pavement condition index (PCI) and requires resurfacing. The combination of Yakutat’s flat topography which does not facilitate effective drainage and its high ground water has resulted in ice blisters in the runway – small, raised areas that result from ice forming under the pavement -- and relatively rapid deterioration of the runway pavement.