

**Steese Highway: Milepost 62-81 Resurfacing and Minor Rehabilitation**

**FY2006 Request: \$4,311,000**  
**Reference No: AMD 40601**

**AP/AL:** Allocation

**Project Type:** Construction

**Category:** Transportation

**Location:** Fox

**Contact:** John MacKinnon

**House District:** Farmer's Loop/Steese Highway (HD 7)

**Contact Phone:** (907)465-6973

**Estimated Project Dates:** 07/01/2005 - 06/30/2010

**Appropriation:** Surface Transportation Program

**Brief Summary and Statement of Need:**

Construct an asphalt surface treatment on the Steese Highway MP 62 - 81, including guardrail repair and sign replacement. This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods.

<b>Funding:</b>	<b>FY2006</b>	<b>FY2007</b>	<b>FY2008</b>	<b>FY2009</b>	<b>FY2010</b>	<b>FY2011</b>	<b>Total</b>
Fed Rcpts	\$4,311,000						\$4,311,000
<b>Total:</b>	<b>\$4,311,000</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$0</b>	<b>\$4,311,000</b>

<input checked="" type="checkbox"/> State Match Required	<input checked="" type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
9% = Minimum State Match % Required		<input checked="" type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

**Operating & Maintenance Costs:**

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	0
<b>Totals:</b>	<b>0</b>	<b>0</b>

**Additional Information / Prior Funding History:**

FY2001 - \$4,880,000.

**Project Description/Justification:**

This project will repair the foundation and drainage problems and will provide a smoother, more durable, and more easily maintained driving surface. This portion of the Steese Highway was constructed in the 1970's and early 1980's. The existing roadbed has developed soft spots, drainage problems, and much of the surfacing material has been lost, making this section of the highway difficult to maintain.