

Cordova: Runway Safety Area Improvements - Drainage**FY2007 Request:****\$5,000,000****Reference No:****AMD 42045****AP/AL:** Allocation**Project Type:** Construction**Category:** Transportation**Location:** Cordova**Contact:** John Torgerson**House District:** Cordova/Southeast Islands (HD**Contact Phone:** (907)269-0727

5)

Estimated Project Dates: 07/01/2006 - 06/30/2009**Appropriation:** Airport Improvement Program**Brief Summary and Statement of Need:**

This is a new FY07 Capital Budget Request. The project will improve drainage and correct safety area issues where drainage catch basins have failed and will repave/pave portions of the runway safety area (RSA). This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods.

Funding:	<u>FY2007</u>	<u>FY2008</u>	<u>FY2009</u>	<u>FY2010</u>	<u>FY2011</u>	<u>FY2012</u>	<u>Total</u>
Fed Rcpts	\$5,000,000						\$5,000,000
Total:	\$5,000,000	\$0	\$0	\$0	\$0	\$0	\$5,000,000

<input checked="" type="checkbox"/> State Match Required	<input checked="" type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
5% = Minimum State Match % Required		<input checked="" type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

Operating & Maintenance Costs:

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	0
Totals:	0	0

Additional Information / Prior Funding History:

None.

Project Description/Justification:

Old inlet boxes and culverts originally placed in the safety area when the airport was constructed approximately 50 plus years ago are failing. Surface water is flowing around the outlets washing away the embankment. The resulting depressions on the surface are large craters that do not meet safety area standards. The glideslope critical area needs to be paved, and portions of the RSA will need to be repaved after the repair work is completed.