

Seward: Regulator Building**FY2010 Request: \$330,000****Reference No: 47756****AP/AL:** Allocation**Project Type:** Construction**Category:** Transportation**Location:** Seward**Contact:** Christine Klein**House District:** Homer/Seward (HD 35)**Contact Phone:** (907)269-0724**Estimated Project Dates:** 07/01/2009 - 06/30/2014**Appropriation:** Airport Improvement Program**Brief Summary and Statement of Need:**

Replace regulator building at Seward Airport. This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods.

Funding:	<u>FY2010</u>	<u>FY2011</u>	<u>FY2012</u>	<u>FY2013</u>	<u>FY2014</u>	<u>FY2015</u>	<u>Total</u>
Fed Rcpts	\$330,000						\$330,000
Total:	\$330,000	\$0	\$0	\$0	\$0	\$0	\$330,000

<input checked="" type="checkbox"/> State Match Required	<input checked="" type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
5% = Minimum State Match % Required		<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

Operating & Maintenance Costs:

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	
Totals:	0	0

Additional Information / Prior Funding History:

None.

Project Description/Justification:

The existing regulator building at Seward Airport was constructed in the 1980's and is in poor condition with leaks throughout the building, resulting in the wetting of electrical components, causing safety issues. The building is in failing condition and is degrading rapidly, succumbing to rot, mold and issues with snow loading. The walls and roof are often wet or saturated. Seasonal flooding at this airport inundates the building, and no personnel can enter it at those times. The building provides little security, as much of the door and frame has rusted away.