

**FY2013 Aviation - Deferred Maintenance Inventory/Backlog**

<b>Project Title</b>	<b>Project Cost (1,000's)</b>	<b>Project Description</b>	<b>Location</b>	<b>Election District</b>
Klawock Airport Hardstands	<b>130.0</b>	Install new hardstands for increased jet traffic in order to minimize pavement damage	Klawock	<b>2</b>
Kake Airport Security Fence Hole Repairs	50.0	Repair over 100 holes in security fence	Kake	5
Gustavus Airport Supplemental Lighted Wind Cone	35.0	Install new supplemental Lighted Wind cone	Gustavus	5
Haines Lease Lot Access Improvement	25.0	Place and compact D-1 on lease lot access taxiway	Haines	5
Gustavus Vegetation Control	20.0	Cut vegetation on Runway Safety Areas 11/29 and 2/20	Gustavus	5
Tree Removal Cordova	50.0	At Cordova Airport identify and remove trees that penetrate runway 16-34 glide slope	Valdez District	5
<b>Total HD 5</b>	<b>180.0</b>			
Stoney River Airport	400.0	Runway rehabilitation	Stoney River	6
Interior Airport Vegetation Control	75.0	Cut Vegetation at five interior airports – Rampart, Stevens Village, Beaver, Hughes, Huslia	Interior	6
<b>Total HD 6</b>	<b>475.0</b>			
Healy River Airport Lighting	<b>300.0</b>	Healy River Airport lighting is in need of updating using conduit and cans instead of direct burial and lights which are stuck in traffic cones	Denali District	<b>8</b>
Lake Louise Airport Dust Palliative	<b>60.0</b>	Apply dust palliative to Lake Louise Airport.	Tazlina District/ Nelchina	<b>12</b>
Kake Vegetation Control	75.0	Cut Vegetation on Runway Safety Area 11/29	Kake	35
Klawock Vegetation Control	35.0	Cut vegetation on Runway Safety Area 2/20	Klawock	35
<b>Total HD 35</b>	<b>110.0</b>			
Old Harbor Airport	150.0	Surface course	Old Harbor	36
Larson Bay Airport	25.0	Lighting system repairs, windsock pole replacement	Larson Bay	36
<b>Total HD 36</b>	<b>175.0</b>			
King Salmon Airport	75.0	Fence and gate repair	King Salmon	37
Chignik Lagoon Airport	25.0	Windsock, poles and markers	Chignik Lagoon	37
<b>Total HD 37</b>	<b>100.0</b>			
Red Devil Airport	<b>150.0</b>	Gravel surfacing	Red Devil	<b>38</b>
Segmented Circle Replacement	250.0	Replace approx. 35 damaged & barrel (old style) segmented circles with current design standard (panel-type circles) for various rural airports.	Northern Region	1-40
D-1 (crushed surfacing) Stockpiles	500.0	Provide D-1 aggregate stockpiles at various airports throughout the Northern Region	Northern Region	1-40
Northern Region Airport Lighting Repairs	250.0	Airport lighting and electrical repairs	Northern Region	1-40

**FY2013 Aviation - Deferred Maintenance Inventory/Backlog**

<b>Project Title</b>	<b>Project Cost (1,000's)</b>	<b>Project Description</b>	<b>Location</b>	<b>Election District</b>
Commissioner's Reserve	70.0	This funding allows the department to respond to unforeseen conditions that require immediate action. This funding is used statewide to respond, as needed, as unsafe conditions arise.	Statewide	1-40
<b>Total HD 1-40</b>	<b>1,070.0</b>			
Peninsula District Repairs	<b>100.0</b>	Replacement of threshold markers and/or edge cones	Seldovia/ Chenega Bay/ Quartz Crk./ Kasilof/ Lawing/ Nanwalek/ Pt. Graham/ Old Harbor/ Larsen Bay/ Ouzinkie/ Karluk / Akhiok	<b>35, 36</b>
Southwest District Lighting Repairs	<b>150.0</b>	Various lighting replacement and repair in Southwest District	Southwest District	<b>36-38</b>
Y-K Delta Airports	<b>500.0</b>	Gravel stockpiles to assist with runway, taxiway, and apron maintenance.	Various	<b>37, 38</b>

<b>Total Aviation Deferred Maintenance Allocation:</b>	<b>\$3,500.0</b>
--	------------------