

**Fairbanks Pioneer Home Deferred Maintenance**

**FY2014 Request: \$782,000**

**Reference No: 57055**

**AP/AL:** Allocation

**Project Type:** Deferred Maintenance

**Category:** Health/Human Services

**Location:** Fairbanks Areawide

**House District:** Fairbanks Areawide (HD 1-5)

**Impact House District:** Fairbanks Areawide (HD 1-5)

**Contact:** Jennifer Klein

**Estimated Project Dates:** 07/01/2013 - 06/30/2018 **Contact Phone:** (907)465-1870

**Appropriation:** Pioneer Homes Deferred Maintenance, Renovation, Repair and Equipment

**Brief Summary and Statement of Need:**

Fairbanks Pioneer Home deferred maintenance

<b>Funding:</b>	<u>FY2014</u>	<u>FY2015</u>	<u>FY2016</u>	<u>FY2017</u>	<u>FY2018</u>	<u>FY2019</u>	<u>Total</u>
Gen Fund	\$782,000						\$782,000
<b>Total:</b>	\$782,000	\$0	\$0	\$0	\$0	\$0	\$782,000

<input type="checkbox"/> State Match Required	<input type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input checked="" type="checkbox"/> On-Going
0% = Minimum State Match % Required		<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

**Operating & Maintenance Costs:**

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	
<b>Totals:</b>	<b>0</b>	<b>0</b>

**Prior Funding History / Additional Information:**

**Project Description/Justification:**

Fairbanks Pioneer Home-Code Alert Upgrade	The existing system will not be supported after FY2014. Upgrade system	\$100,000
Fairbanks Pioneer Home-Gutter and Downspout Installation	It is recommended that eaves be added where required on the building perimeter to direct water into down spouts and subsequently to a drywell system or piped away from the building.	\$42,000
Fairbanks Pioneer Home-Replace Sanitary Waste Lines and Kitchen Grease Trap	Replace sanitary waste lines in original building, grease trap in the kitchen and lift station.	\$200,000
Fairbanks Pioneer Home-Pavement Repairs & Parking Expansion	General repairs are required to restore asphalt-paved surfaces on the property, which include the access road and parking lot surfacing and expansion.	\$120,000
Fairbanks Pioneer Home-	Entry doors are not secure. Replacement	\$75,000

**Fairbanks Pioneer Home Deferred Maintenance****FY2014 Request:****\$782,000****Reference No:****57055**

Front Entry Doors	is needed for the safety & security of the residents.	
Fairbanks Pioneer Home-Main Facility-Replace Kitchen Floor Tile	Replace the kitchen quarry tile as it is leaking in the dish washing area and the tile has exceeded its useful life.	\$95,000
Fairbanks Pioneer Home-Mechanical Repairs	Replace original building's air handling units as they have exceeded their expected useful life, and are requiring frequent repairs.	\$150,000
<b>TOTAL</b>		<b>\$782,000</b>

Each building deficiency for every facility is rated in terms of urgency, fire/life/safety, security, building integrity, and mission efficiency. Together, these criteria are used to prioritize each project. Priorities given are generally followed, but may be changed due to higher emerging needs that may arise throughout the year.