

Haines - Airport Drainage Improvement and Taxiway, Runway and Apron Rehabilitation, and Fencing

FY2014 Request: \$2,000,000
Reference No: 49104

AP/AL: Allocation

Project Type: Construction

Category: Transportation

Location: Haines

House District: Southeast Islands (HD 34)

Impact House District: Southeast Islands (HD 34)

Contact: Steven Hatter

Estimated Project Dates: 07/01/2013 - 06/30/2018

Contact Phone: (907)269-0730

Appropriation: Airport Improvement Program

Brief Summary and Statement of Need:

This project will be used to address pavement problems on the apron, taxiway and runway, fix drainage issues and replace damaged fencing.

Funding:	<u>FY2014</u>	<u>FY2015</u>	<u>FY2016</u>	<u>FY2017</u>	<u>FY2018</u>	<u>FY2019</u>	<u>Total</u>
Fed Rcpts	\$2,000,000						\$2,000,000
Total:	\$2,000,000	\$0	\$0	\$0	\$0	\$0	\$2,000,000

<input type="checkbox"/> State Match Required	<input type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input checked="" type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
0% = Minimum State Match % Required		<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

Operating & Maintenance Costs:

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	0
Totals:	0	0

Prior Funding History / Additional Information:

Project Description/Justification:

Pavement on apron and sections of taxiway and runway has a low PCI and requires resurfacing. Subsurface drainage structures have settled and the resulting drainage deficiencies cause frost heave problems, humps in the pavement and flooding on the apron. Drainage problems can only be solved through elevating the grade of the apron. Some existing lease lots will be impacted resulting in a loss of one existing lot. In order to provide sufficient lease lots for existing tenants, the airport parking lot will be relocated from the apron to its ultimate location in accordance with the airport's master plan.