

King Salmon - Runway Pavement Reconstruction

FY2014 Request: \$4,000,000

Reference No: 56966

AP/AL: Allocation

Project Type: Construction

Category: Transportation

Location: King Salmon

House District: Dillingham/Illiamna (HD 36)

Impact House District: Dillingham/Illiamna (HD 36)

Contact: Steven Hatter

Estimated Project Dates: 07/01/2013 - 06/30/2018

Contact Phone: (907)269-0730

Appropriation: Airport Improvement Program

Brief Summary and Statement of Need:

Pavement rehabilitation in touch down areas of the main runway.

Funding:	<u>FY2014</u>	<u>FY2015</u>	<u>FY2016</u>	<u>FY2017</u>	<u>FY2018</u>	<u>FY2019</u>	<u>Total</u>
Fed Rcpts	\$4,000,000						\$4,000,000
Total:	\$4,000,000	\$0	\$0	\$0	\$0	\$0	\$4,000,000

<input type="checkbox"/> State Match Required	<input checked="" type="checkbox"/> One-Time Project	<input type="checkbox"/> Phased - new	<input type="checkbox"/> Phased - underway	<input type="checkbox"/> On-Going
0% = Minimum State Match % Required		<input type="checkbox"/> Amendment	<input type="checkbox"/> Mental Health Bill	

Operating & Maintenance Costs:

	<u>Amount</u>	<u>Staff</u>
Project Development:	0	0
Ongoing Operating:	0	0
One-Time Startup:	0	
Totals:	0	0

Prior Funding History / Additional Information:

No prior funding history

Project Description/Justification:

Pavement Condition Report from statewide pavement engineer determined the existing surfacing condition is below standards and identified concern for foreign objects and debris (FOD) and high maintenance expense.